

- 4 1/2" or 5" Grinder
- Carbide Tipped Scriber
- Center Punch
- Chipping Hammer
- Combination Square
- Ear Plugs (optional, not Electric)
- Fillet weld gauge set
- Flashlight- Mini-mag
- Hammer
- Hex key set (Allen Wrenches)
- Leather Apron (covering waist to ankles, optional)
- Leather Work Gloves
- Leather High Top Boots (preferable steel toe)
- Leather Jacket (covering arm and chest to apron)
- Metal Gauge
- Multimeter kit (Ohms, Volts, MFD, Temp, Amps) with Alligator Clips
- Nut driver set
- Pliers - Arc joint
- Pliers - 12" Lineman
- Pliers - Welpers (Mig Pliers)
- 25' extension cord (grounded)
- 90° magnet
- Pliers- Needle nose
- Pliers- Side Cutters
- Pliers - 8" (or vise grips)
- Pocket level
- Putty knife
- Rod Pouches (optional)
- Safety glasses

- Scientific calculator, TI-30
- Screwdriver -combination (4-in-1)
- Socket set, 1/4" and 3/8"
- Striker or Spark Lighter
- Tip Cleaners (standard set)
- Tape measure, 25ft
- Tool Pouch/Rolling Tool Box
- Utility Knife (not pocket knife)
- Welding & Cutting goggles with lens shade #4 or #5
- Welding gloves (Tig and Mig)
- Welding helmet & Lens shade #10, #11 or #12
- Wire Brush
- Wrap Around (pipe wrap)
- Wrench - adjustable end wrench, 12"
- Wrench -adjustable end, 8"
- Combination Wrench Set (standard and metric)t